





Tegnforklaring

- | | |
|-----------------------|------------------------------|
| Betongheller 30x30x7 | Drensrenne |
| Betongheller 30x30x5 | Kantstein uten vis |
| Gressarmering | Kantstein med vis |
| Singel | Asfalt |
| Sykkelparkering 5 stk | Fallunderlag |
| Plen | Nye trær |
| Grasbakke | - Alnus glutinosa 'Sakari' E |
| Eksisterende buskfelt | - Søylesvarter |
| Hekker | - Carpinus betulus |
| - Agnbøk | Plantefelt: |
| Nye koter 20cm | - busker |
| Nye koter 1 m | - stauder |
| Glassrekkverk | - klatreplanter |
| Rekkverk | Drenerende masser |
| Fotskraperist | Grusdekke |

Tiltakshaver:		
...		
Tiltakets adresse:		
St. Joseph		
Tegningen gjelder:		
Landskapsplan		
Dato:		
7.4.2025		
G.nr. :	B.nr.:	Målestokk:
...	...	1:200 A1
Sign.	Revisjon	
...	...	

